




EXPOSURE TO MOLD AND ASBESTOS
Non-Directional Beacon, Rutland, Vermont




**UNSTABLE BUILDING AND INFRASTRUCTURE
Allegheny County Airport, Pennsylvania**



**UNSTABLE TOWER LOCATED NEAR PRIVATE RESIDENCE
Allegheny County Airport, Pennsylvania**



LEAKING CEILING
Denver TRACON



DETERIORATING STRUCTURE

Very High Frequency Omnidirectional Range, Litchfield, Michigan



EXPOSURE TO MOLD AND ASBESTOS
Non-Directional Beacon, Rutland, Vermont



IMPROPERLY HOUSED EQUIPMENT
Instrument Landing System Glideslope, Jackson, Michigan



BUILDING DISREPAIR
Chicago Midway Radar



UNSTABLE INFRASTRUCTURE
Allegheny County Airport, Pennsylvania



IMPROPERLY HOUSED EQUIPMENT
Allegheny County Airport, Pennsylvania



BUILDING DISREPAIR

Very High Frequency Omnidirectional Range, Selawik, Alaska



**UNSTABLE INFRASTRUCTURE IN UNSECURED LOCATION
Outer Marker, Peachtree Dekalb Airport, Georgia**



BUILDING DISREPAIR
Localizer Building, Jackson, Michigan



MOLD AND CORROSION

Instrument Landing System Localizer Building, Toledo, Ohio



WATER DAMAGE NEAR EQUIPMENT
Instrument Landing System Glideslope, Jackson, Michigan